

Oil Field Environmental Incident Summary

Incident: 20150818102048 **Date/Time of Notice:** 08/18/2015 10:20

Responsible Party: XTO ENERGY INC.

Well Operator: XTO ENERGY INC.

Well Name: BOOMER FEDERAL 34X-35G

Field Name: LOST BRIDGE

Well File #: 26326

Date Incident: 8/17/2015 **Time Incident:** 07:00

Facility ID Number:

County: DUNN

Twp: 148

Rng: 97

Sec: 35

Qtr:

Location Description:

Submitted By: Kaylan Dirkx

Received By:

Contact Person: Kaylan Dirkx
PO Box 1589
Sidney, MT 59270

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Tank Overflow

Release Contained in Dike: Yes - Within Dike

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil						
Brine	99	Barrels	99	Barrels	99	barrels
Other						

Description of Other Released Contaminant:

Inspected:

Written Report Received: 1/8/2016

Clean Up Concluded: 8/20/2015

Risk Evaluation:

None- spill was contained within lined metal berm and has been cleaned up.

Areal Extent:

Potential Environmental Impacts:

None- spill was contained within lined metal berm and has been cleaned up.

Action Taken or Planned:

Well was shut in and vac truck was dispatched to collect free fluids.

Wastes Disposal Location: Free fluids disposed at Kulish 14-2 SWD
Gravel inside the lined metal berm will be removed and disposed at
Chimney Butte Disposal.

Agencies Involved:

Updates

Date: 8/18/2015 **Status:** Reviewed - Assigned to Other Agency

Author: Stockdill, Scott

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

According to the incident summary this spill remained within the dikes on location. NDIC retains oversight.